

P-216

Concept® Low VOC Speed Clear Clear

DCU2042

DCU2042 Low VOC Speed Clear is the fastest, most productive clear in the PPG family of clear finishes.

DCU2042 cuts your bake time in half and can be polished if needed within minutes after cooling down.



Features

- Fastest Baking Clear
- Polish Shortly After Bake
- Low 4.2 VOC

Advantages

- Double Your Booth
 Production
- Repairs Completed Quickly
- Complies With Current Regulations

Benefits

- Increased Revenue
- Fast Delivery Time
- Allows Greater Productivity
 In Compliant Areas

Compatible Surfaces

DCU2042 may be applied over:

- DELTRON® (DBU) Universal Basecoat
- DELTRON® 2000 (DBC) Basecoat
- CONCEPT® (DCC) Acrylic Urethane

Required Products

	Hardeners	
Hot Temperature / Force Dry	DCX9	
General Purpose	DCX61	
	DT Reducers	
Cool Temperature (60 – 70°F / 16 – 21°C)	DT860	
Medium Temperature (65 – 80°F / 18 – 27°C)	DT870	
Warm Temperature (75 – 90°F / 24 – 32°C)	DT885	
Hot Temperature (85°F / 29°C and above)	DT895	



DCU2042 Directions for Use

Preparation:

Where VOC limits allow a maximum of 5.0 #/US Gal. for multi-stage systems, reduce DBU Color 150% with DRR Reducer or DBC Color 100% with DT Reducer. Refer to the Product Information Bulletin of the color system for its application, dry times, and blend recommendations. (See P-175CA for DBC and P-152 for DBU Color).

Mixing Ratios:					
		Standard Mix			
		DCU2042 : DT Reducer : DCX9 or DCX61			
		4 : 1 : 1			
		Flexible Parts with DX814			
		Full panel only when part is off the vehicle*. Mix DCU2042 with DX814 Universal Flexibilizer in the following ratio:			
	Π	DCU20424 : DT Reducer : DCX9 or DCX61 : DX814			
		4 : 1 : 2 : 1			
		Flexible Parts without DX814			
		DCU2042/DCX9 may be used on flexible parts without DX814			
		DCU20424 : DT Reducer : DCX9 : DX814			
		4 : 1 : 1 : -			
		*It is not necessary to add DX 814 to DCU 2042 when the part is already mounted on the vehicle.			
Pot Life:					
		1 - 1 ¹ / ₂ hours at 70°F (21°C) for standard mix			
	A	1 - 2 hours at 70°F (21°C) when flexibilized with DX814			
	$\mathbf{\Theta}$	1 - $1^{1/2}$ hours at 70°F (21°C) when flexibilized without DX814			
Additives:					
		DCU2042 <u>cannot</u> be tinted. Use D814 Plasticiser to flexibilize DCU2042 - See mixing ratios DX84 Enhancer, DX87 Extender or DXR81 Accelerator may be added to DCU2042 up to ¹ / ₂ U.S. fl. Oz. Per ready-to-spray quart.			
	AB				
Appliction Coats:					
		Apply: 2 wet coats			
Air Pressure:					
	≥	HVLP 10 psi at the air cap			
		Conventional 45 – 55 psi at the gun			
Spraygun Set-up:					
		Fluid Tip: 1.3 - 1.5 mm or equivalent			
		Film Build Per Wet Coat: $2.4 - 2.8$ mils			
		Dried Film Build Per Coat: 1.2 – 1.4 mils			

Directions for Use

Drying Times:











Between Coats:	5 - 10 minutes @ 70°F (21°C)			
Before Baking:	0 – 5 minutes @ 70°F (21°C)			
Dust Free: 70°F (21°C)	20 – 25 minutes (4:1:1 w/DCX61) 30 – 35 minutes (4:1:1 w/DCX9)			
Dry to handle: 70°F (21°C)	60 – 70 minutes (4:1:1 w/DCX61) 70 – 80 minutes (4:1:1 w/DCX9)			
140°F (60°C)	30 minutes			
Tape Time: 68°F/ 20°C 140°F (60°C)	5 – 6 hours 15 – 20 minutes			
Through Dry: 68°F/ 20°C 140°F (60°C)	8 hours 15 – 20 minutes			
IR (Infrared): Medium Wave Short Wave	15 minutes 8 minutes			
Polishing: Air Dry Force Dry	Allow 12 hours @ 70°F (21°C) After Cool Down			
Repair and Recoat:	8 hours air dry @ 70°F (21°C) or, after the force dry/cooling cycle ends plus 2 additional hours. After 3 days, DCU2042 must be sanded before recoating			
	with primer, color, or clear are quoted for metal temperature. Additional time must be o allow metal to reach recommended temperature.			

Equipment Cleaning:					
		Spray guns, gun cups, storage pots, etc., should be cleaned thoroughly after each use wit DX590 All Purpose Clean Up Solvent, DT Reducers, or DTL Thinners.			
Technical Data:	Vi	C (Dealrage)		4.02 lbs / U.S.Gal	
		DC (Package) DC less exempt solvents	(Applied 4:1:1)	4.02 lbs / U.S.Gal (w/DCX61) 3.96 lbs / U.S.Gal (w/DCX61) 4.07 lbs / U.S.Gal (w/DCX9)	
	То	tal Solids by Volume	(Applied 4:1:1)	41.5% (w/DCX61) 41.5% (w/DCX9)	
		. Ft Coverage / US Gal (1 mil 100% Transfer effi	iciency)		
		x	(Applied 4:1:1)	666 (w/DCX61) 665 (w/DCX9)	
Resistance Testing:		DCU2042 Clearcoat. Al	l resistance results w	t <i>UNIPRIME®</i> and topcoated with rere obtained after DCU2042 Urethane tures (70°F/21°C).	
Important:	Before opening the packages, be	sure you understand the	e warning messages o	s before the product can be used. on the labels of all components, since the	

mixture will have the hazards of all its parts. Improper spray technique may result in a hazardous condition. Follow spray equipment manufacturer's instructions to prevent personal injury or fire. Follow directions for respirator use. Wear eye and skin protection. Observe all applicable precautions. See Material Safety Data Sheet and Labels for additional safety information and handling instructions.

EMERGENCY MEDICAL OR SPILL CONTROL INFORMATION (304) 843-1300; IN CANADA (514) 645-1320

Materials described are designed for application by professional, trained personnel using proper equipment and are not intended for sale to the general public. Products mentioned may be hazardous and should only be used according to directions, while observing precautions and warning statements listed on label. Statements and methods described are based upon the best information and practices known to PPG Industries. Procedures for applications mentioned are suggestions only and are not to be construed as representations or warranties as to performance, results, or fitness for any intended use, nor does PPG Industries warrant freedom from patent infringement in the use of any formula or process set forth herein.



PPG Automotive Refinish

World Leaders In Automotive Finishes

PPG Industries 19699 Progress Drive Strongsville, OH 44149

PPG Canada Inc. 2301 Royal Windsor Drive Mississauga, Ontario L5J 1K5